Work Ord October-25-11		577		*75577*							Page 1			
tem ID: Revision ID: tem Name:	D3325-041 Basket Lid As	sembly		Accept	*N900	040	100	* s	etup Star	* *N	S1* S2*			
tart Date: Required Date Reference:	25/10/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item II Customer:	D:	V	V // V /-	oth-) IN	5 /			
approvals:	Process Pla	n: <u>M</u> .C.J	Date:	Tooling: SPC (Y/N):	Da			R	tun Star Stop	[]	R1* R2*			
equence ID/ Vork Center I Draw Nbr		Operation Description		Set Up/ Run Hours	Tool ID		Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp			
D3325	Rev	ision Nbr B												
100 Large Fab		QtyPart N 2D3325-1 3D3325-3 2D3325-5	umber Description EndTube	0.00 0.00 Batch	ge11.11.0	23	((I)	0					
		3-Drill and A/R4130S	all markings from materiald Weld as per Dwg D3325 steel Rod M /1887							:				

	.copaco.												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PR	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
			30 Mary 14.00										
Part No	:	PAR #:	Fault Categ	jory:	_ NCR: Yes	No DQ	A:	_ Date: _					
	Res	solution:	Disposition	:	_ QA: N/C C	osed:		Date: _					
NCR:			WORK ORDE	R NON-CONFORMA	IANCE (NCR)								
DATE	CTED	Description of NC		Corrective Action Section		Verific	cation		Approval				
DATE	STEP	Section A	Initial	Action Description Chief Eng	Sign & Date	k Secti	on C	Chief Eng	QC Inspector				
				. *					·				
							-						
				,. •				·					
	1 1		1 1		ı	1		1	1				

Work Order ID 75577 *75577* Page 2 October-25-11 3:11:45 PM Item ID: D3325-041 Accept *N900040100* Setup Start **Revision ID:** Item Name: Basket Lid Assembly Start Qty: 1.00 **Start Date:** 25/10/2011 **Cust Item ID: Required Date: 08/11/2011** Req'd Qty: 1.00 **Customer:** Reference: Run Process Plan: Approvals: Date: Tooling: Date: SPC (Y/N): Date: Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Otv Oty Number Stamp 110 QC9- Inspect visual per QSI004- Fusion Welds 0.00 *110* 0.00 Memo Quality Control 120 QC5- Inspect part completeness to step on W/O 0.00 *120* OC 0.00 Memo Quality Control

121

Pressure Wash per QSI005 4.3

0.00

191

HandFinish

Memo

0.00

Hand Finishing

	•												
W/O:		P	WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
			·										
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:								
	Re	esolution:	Dispositio	n:	QA: N/C CI	osed:		Date: _					
NCR:			WORK ORD	ER NON-CONFORMAN	ICE (NCR)							
DATE	STEP	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval				
DAIL	3121	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	ion C	Chief Eng	QC Inspector				
				· · · · · · · · · · · · · · · · · · ·									
		·											
								`					

Work Order ID 75577 October-25-11 3:11:45 PM			*75577*						Page :	
Item ID: Revision ID:	D3325-041	-		Accept	*N90004	1 0100*	Setup	Start	*NS1*	
Item Name:	Basket Lid Ass	sembly						Stop	*NS2*	
Start Date: Required Date: Reference:	25/10/2011 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				14(7)	
Approvals:	Process Pla	n:	Date:	Tooling: _ SPC (Y/N):	Date:		Run	Start Stop	*NR1* *NR2*	
Sequence ID/ Work Center II 130 *130* Powdercoat Powder Coating		FINISH TIM ***** 2ND COAT: START TIM	E:	Set Up/ Run Hours 0.00 0.00 0.00 0.00 0.00 0.00 0.00	Tool ID To	ool# Plan Acc Code Qty		-	Reject Insp. Number Stamp	
140	•	QC3- Inspect Part Finish	-	0.00			<i></i>	/	,	

Quality Control

Memo

0.00

	•								
V/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
10									
Part No	:	PAR #:	Fault Categ	gory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	Reso	olution:	Disposition	n:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC	Initial	Corrective Action Sect Action Description	ion B Sign &		cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector
						!			
									

October-25-11				"/b:)//°						Page 4
Item ID: Revision ID:	D3325-041	a mile.		Accept	*N90004	L 0100)*	Setup	Start Stop	*N!	==== S1*
Item Name: Start Date: Required Date: Reference:	Basket Lid As 25/10/2011 : 08/11/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				З	, ^ N ;	S2*
Approvals:	Process Pla	ın:	Date:	Tooling: SPC (Y/N):	Date:			Run	Start Stop	*NI *NI	R1* R2*
Sequence ID/ Work Center I 150 *150* Packaging Packaging	D	Operation Description Identify as per dwg & S	tock Location: <u>CA</u> W/0 75571	Set Up/ Run Hours 0.00	Tool ID To	ol # Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
160 *160* QC Quality Control		QC21- Final Inspection Memo	- Work Order Release	0.00		ř			!	14/	14
										Λ	

Dart /	Aeros	pace	Ltd
--------	-------	------	-----

									· · · · · ·			
W/O:			WORK ORDER CHANGES									
DATE	STEP	PROC	CEDURE CHA	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						,						
												
Part No	•	PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:				
		esolution:	n: Disposition: QA: N/C Closed: Date:									
NCR:		W	ORK ORD	ER NON-CONFORMA	NCE (NC	R)						
DATE	CTED	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval			
DATE	STEP	Section A	Initial Action Descript Chief Eng Chief Eng		Sign Date	& Section C		Chief Eng	QC Inspector			
								-				

4. 4

Picklist Print

October-25-11 3:11:50 PM

Work Order ID: 75577

75577

D3325-041

Parent Item Name: Basket Lid Assembly

D3325-041

Start Date: 25/10/2011

Required Date: 08/11/2011

Page 1

Start Qty: 1.00

Required Qty: 1.00

Comments:

Parent Item:

IPP Rev:A05.02.09New issueKJ/JLM

IPP Rev:B 08-12-16 attach DEO DD verified by:EC

	Component Item ID/ tem Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
4	03328-1 *\(\mathbb{T}\)3328-1* Basket Hinge		Manufactured	No			100	Each	23.0000	**	$\frac{2}{M}$	11/10	106	
					Location WA005	33871	Loc	Oty 23 23	Loc Code	_	(2 _V)			
4	*D3349-1 *D3349-1* pacer Bushing		Manufactured	No			100	Each	28.0000	**		4 11	o s	6
					Location WA005	44401	Loc	Oty 28 28	Loc Code	_	(a)		·	
4	*D3352-1 *D3352-1* abel Plate		Manufactured	No			100	Each	14.0000	1 **		H 11	/10	126
					Location WA005	41925	<u>Loc</u>	<mark>Oty</mark> 14 14	Loc Code	_				
7	*D3367-1 *D3367-1* Mounting Bracket		Manufactured	No			100	Each	20.0000	2 **		W 11,	10/	26
					Location WA005	43228	Loc	Otv 20 20	Loc Code		(DX)			

	•											
W/O:		The state of the s	WO	RK ORDER CHANGE	S							
DATE	STEP	PRO	CEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes							
			Disposition: QA: N/C Closed: Date:									
NCR:			VORK ORDE	R NON-CONFORMA	NCE (NCR)						
DATE	OTED	Description of NC	Corrective Action Section		Verific	cation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	I	ion C	Chief Eng	QC Inspector			
i												
		·										
	:											

Picklist Print

October-25-11 3:11:50 PM

Page 2

Work Order ID: 75577

75577

Parent Item:

D3325-041

D3325-041

Parent Item Name: Basket Lid Assembly

Start Date: 25/10/2011

Required Date: 08/11/2011

Start Qty: 1.00

**

Required Qty: 1.00

M4130NTS0.500W.035

Purchased

No

100

f

39.2488

270.9988

20.5416

21.62274

112786

M4130NTS0 500W 035

4130 Square tube .500 x .500 x .035w

Location Loc Oty MAT034 270.9988 109127 216 109385 15.75


Loc Code

October-25-11 3:11:50 PM

Shop Packet Print

Page 2


W/O:			WO	RK ORDER CHANGI	ES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•							
Part No):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
			Disposition	າ:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCF	₹)			
DATE	STEP	Description of NC	L	Corrective Action Section	on B		cation	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Date		ion C	Chief Eng	QC Inspector




W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHAN		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
								Frod Wigi						
								1						
								<u> </u>						
			,											
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes No DQA: Date:									
	Res	solution:	Disposition	II	QA: N/C	Closed:	•	Date: _						
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (NC	R)								
		Description of NC		tion B	Verif	ication	Approval	Approval						
DATE	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng	ion Sign & Date		tion C	Chief Eng	QC Inspector					
·														
. .														



DESIGN AH	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO,	
CHECKED,	APPROVED	DRAWING NO.	REV. 8
4	1 #	D3325	SHEET 2 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



VIEW A-A



DEO ATTACHED




W/O:			W	ORK ORDER CHANG	ES					
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								100 mg	,	
···,										
David Na		D. 1.			NOT 1/					
Part No						NCR: Yes No DQA: Date:				
				Disposition: QA: N/C Closed: Date:						
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	H)				
DATE	STEP	Description of NC	Initial	on B Sign		cation	Approval	Approval		
		Section A	Chief Eng	Action Description Chief Eng	Dat	J JCLIUII C		Chief Eng	QC Inspector	
				<u> </u>						
									•	
· · · · · · · · · · · · · · · · · · ·	 									

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



DESIGN PH	DRAWN BY	DART AEROSPA HAWKESBURY, ONTARIO,	
CHECKED	APPROVED	DRAWING NO.	REV. 8
At .	├	D3325	SHEET 3 OF 3
DATE		TITLE	SCALE
05.04.25		BASKET LID ASSEMBLY	1:4



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:	1	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	WO	RK ORDER CHANG	EC				
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							1	Frod Mgi	
							!		
				·					
			······································						
Part No	•	PAR #:	Fault Categ	ory:	_ NCR: Yes	No DQ	A:	Date:	
		esolution:							
NCR:		,	WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
		Description of NC			Section B Verif			Approval	Approval
DATE	STEP Description of NC Section A	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		ion C	Chief Eng	QC Inspector
									:
		· .							
								!	

75577

DRAWING	NO.	TITLE		REV. B	DART AE	ROSPACE LTD		D.E.O. NO.		SHEET NO.	SCALE
D3325		BASKET LIC	ASSEMBLY	,	ENGINEE	RING ORDER		D3325-B-1		SHEET 1 OF 1	NTS
DRAWN	AJS		CHECKED	4	MFG. APPR.	77	APP	PROVED	140	DE APPR.	
DATE	08.11.	28	DATE	08.11.28	DATE	08.12.01	DAT	E	08.12.01	DATE 08.12-01	

1) SHEET 1 MODIFY PARTS LIST AS SHOWN:

PART LIST FOR D3325-041 BASKET LID ASSEMBLY

Part No.	Quantity	Description
	\\	

IS:

	V						
MS20600AD4W5	32	RIVET					

WAS:

	 1	L
MS20600AD4W3	32	RIVET

2) UPDATE SHEET 3 DETAIL B ACCORDINGLY.

COPYRIGHT © 2008 BY DART AEROSPACE LTD

THIS DOGMENT IS PRIVATE AND CONTIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS

NOT TO BE USED FOR ANY PUPPINGE OR COMPLIANCE TO DAILY OTHER PERSON MITHOUT

WRITTEN PERMISSION FROM DART AEROSPACE LTD.

D	ar	t /	۹e	ro	sp	ac	е	Ltd
---	----	-----	----	----	----	----	---	-----

									•		
W/O:	Ţ		V	ORK ORDER CHANGE	ES						
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No:		PAR #:	Fault Ca	legory:	NCR: Yes	NCR: Yes No DQA: Date:					
	R	esolution:	Disposition: Q			QA: N/C Closed: Date: _					
NCR:	,	V	VORK OR	DER NON-CONFORMA	NCE (NC	R)					
DATE	STEP	Description of NC		Corrective Action Section		Verifi	Verification Approva		Approval		
DAIL	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector		
							:				
						:					